

EARTH TECH DAILY SAFETY MEETING

DATE: 0700 TIME: 5/19/05 CLIENT: US EPA REG 5
 SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task ***listen to others if there is a concern in exclusion zone***

PROTECTIVE CLOTHING/EQUIPMENT: Level C/half face respirator, safety glasses, n-dex gloves, leather or cotton gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control), ET does personnel air monitoring (as per "Neg Exp Asmt memo"), *ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Steve Padua
 Craig Peleasant
 Brad Henrich
 Jason Cox
 Steve R. Adelman
 Lori Ash

[Signatures]
 George By
 Steve R. Adelman
 Lori Ash

Meeting Conducted By:

[Signature]



US EPA RECORDS CENTER REGION 5



467463

*roll off
 *Topsoil,
 Seeds
 Straw mat
 *lots of
 staples

*6 real pb
 again